PARKER GAS CO. INC.
Feel Comfortable With Us

www.parkergas.com

INVOICE

Customer #:	54978
Payment Terms:	Net 30
Invoice #:	6302057
Invoice Date	2026-10-02
Total Due	$1,297.63

Make Check Payable to: Parker Gas Co. Inc.

Amount Enclosed: $ _____

BYRON HAYNES (RENTAL)

Attn: BYRON HAYNES
2275 MICRO RD W
SELMA, NC 27576

Remit To:
Parker Gas Co. Inc.
PO Box 2590
Clinton, NC 28329-2590

00000549780006302057000012976300001297632

Customer Name	Delivery/Service Address	Cust #	Invoice #	Inv Date
	2312 MICRO RD WEST - SELMA, NC 27576	54978	6302057	2026-10-02

Quantity	Item Number	Description	Unit Price	TOTAL
1.00	TRUCK SUPPLIES	TRUCK SUPPLIES	$9.7500	$9.75
1.00	RHEEM WATER HEA	RHEEM WATER HEATER-40 GALLON TALL Serial Number: Q102507054	$770.4200	$770.42
1.00	3/8IN FLARE X 1/2IN	ADAPTER-3/8" FLARE X 1/2" MPT	$3.3200	$3.32
1.00	3/4IN GALV UNION	GALVANIZED UNION-3/4" SCH 40	$13.4900	$13.49
1.00	3/4IN BALL VALVE W	3/4IN CUTOFF FULL PORT WITH LONG HANDLE	$22.1900	$22.19
2.00	3/4IN X 2IN GALV NIP	GALVANIZED NIPPLE-3/4" X 2"	$2.7900	$5.58
3.00	Labor-1	Labor-1 Person	$110.0000	$330.00
1.00	White Goods Tax	White Goods Tax	$3.0000	$3.00
1.00	3/4IN SHARKBITE C	3/4IN SHARKBITE COUPLING	$16.3000	$16.30
1.00	3/4IN SHARKBITE 24	3/4IN SHARKBITE 24IN FLEX CONNECTOR	$41.7200	$41.72
		Johnston County NC Sales Tax:		$24.26
		NC State Sales Tax:		$57.60

Tank/Equipment: Water Heater -

For Fuel or Service At:
2312 MICRO RD WEST - SELMA, NC 27576

Sub Total	$1,215.77
Charges	$0.00
Tax Total	$81.86
TOTAL DUE	$1,297.63

ACCOUNT BALANCE	$0.00

10/02/2026 - Technician: Nathan Piercy - Work Performed: Repair - 10/2/26 Tech found thermocouple went bad. They don't make a replacement for that year model. Tech removed old water heater. Tech installed new 40 gallon Rheem water heater. S/N : Q102507054 Tech installed existing cutoff and 3/8 copper to new water heater. Tech installed 3/4 cutoff long handle and 3/4 flex hoses to hot and cold water side. Tech performed leak check. NO leaks found. Tech lit appliance. Tech informed customer that they will need to have a plumber come and fix cold water side which is 3/4 copper. Schedule for P3 once customer has cold water side fixed.