



Family Owned & NC Grown

www.gbenergy.com

REMIT TO:

G&B ENERGY
P.O. BOX 811
ELKIN, NC 28621



G&B ENERGY - MILLS RIVER
5046 BOYLSTON HIGHWAY
MILLS RIVER, NC 28759
828-891-7371

*** SERVICE INVOICE *** 60234 ***

BRUCE REDLER
170 OAKANOAH CT
BREVARD, NC 28712

ACCT# 615974 9/06/24

RETURN TOP PORTION WITH YOUR REMITTANCE.



SVC# 1

QUANTITY	DESCRIPTION	AMOUNT
1.000	TOTAL MATERIAL USED	533.00
1.000	BALL VALVE 1/2 X 1/2	
2.000	NIPPLE 1/2	
2.000	ELL 90 1/2	
1.000	UNION 1/2	
1.000	CAP 1/2" BLACK STEEL	
1.000	MEGAPRS ADAPT PXMPT 1/2 QVG-25101	
1.000	NIPPLE 1/2 X 2	
1.000	NIPPLE 1/2" X 8"	
1.000	TEE 3/4 X 3/4 X 1/2	
1.000	ELL 90 3/4 X 1/2	
1.000	NIPPLE 3/4 X 3	
15.000	PVC PIPE S40 2"	
4.000	PVC EL 2" 90	
1.000	PVC COUPLING 2"	
1.000	PVC REDUCER 3 X 2	

* CONTINUED * PAGE 1



Family Owned & NC Grown

www.gbenergy.com

REMIT TO:

G&B ENERGY
P.O. BOX 811
ELKIN, NC 28621


G&B ENERGY - MILLS RIVER
5046 BOYLSTON HIGHWAY
MILLS RIVER, NC 28759
828-891-7371

*** SERVICE INVOICE *** 60234 ***

BRUCE REDLER
170 OAKANOAH CT
BREVARD, NC 28712

ACCT# 615974 9/06/24

RETURN TOP PORTION WITH YOUR REMITTANCE.



SVC# 1

QUANTITY	DESCRIPTION	AMOUNT
1.000	NIPPLE 1/2 X 36"	
1.000	PLUMBING ISOLATION KIT 3/4"	
1.000	CONDENSING 199,000 BTU NG RINNAIWHRX199INSD.BA-063001	1595.00
1.000	PRESSURE TEST	
	TOTAL PARTS	2128.00
	TOTAL LABOR 10.00 HOURS	1200.00
	NC SALES TAX	224.64
	WHITE GOODS TAX	3.00

<<< TOTAL CHARGE FOR INVOICE # 60234 >>> 3555.64

SITE:BRUCE REDLER/170 OAKANOAH CT./BREVARD NC 28712
DISPATCH DATE: 9/06/24
CALL REASONS: INSTALLATION
WORK PERFORMED: INSTALLED WATER HEATER

REMOVED TANK WATER HEATER AND INSTALLED RX199IN TANKLESS

* CONTINUED * PAGE 2



Family Owned & NC Grown

www.gbenergy.com

REMIT TO:

G&B ENERGY
P.O. BOX 811
ELKIN, NC 28621


G&B ENERGY - MILLS RIVER
5046 BOYLSTON HIGHWAY
MILLS RIVER, NC 28759
828-891-7371

*** SERVICE INVOICE *** 60234 ***

BRUCE REDLER
170 OAKANOAH CT
BREVARD, NC 28712

ACCT# 615974 9/06/24

RETURN TOP PORTION WITH YOUR REMITTANCE.



SVC# 1

QUANTITY	DESCRIPTION	AMOUNT
	LEAK TEST GOOD REPLACED 2 THERMOCOUPLES ON OUTDOOR FIREPLACE	

PAGE 3