



# Leak Check Report

**Customer No.:** 11310750                      **Customer**                      Patricia Jenson  
**Name:**  
**Date of**                      10-10-2025 11:56 AM                      **Ticket**                      30973988  
**Inspection:**                      **Number:**  
**CSC Location:**                      6402 Lumberton, NC

## Customer Information

**Service Address:** 520 Caton Road Lumberton NC 28360  
**Billing Address:** 520 Caton Road Lumberton NC 28360  
**Tank ID::** 2999914  
**Tank**                      RINNAI RE180EP  
**Description:**

## Test Results

**Type of Test:** 0-30 High Pressure Test                      **Line Presssure:**                      11 psi  
Gauge  
**Start**                      5 psi                      **End Pressure:**                      5 psi  
**Pressure:**  
**Start Time:** 10-10-2025 11:42 AM                      **End Time:**                      10-10-2025 11:48 AM  
**Test Status:** Pass                      **Tagged &**  
**locked:**

**Reason:**  
Leak Check includes all stages

## Employee Acknowledgement

**Employee**                      Harbin, Jamie  
**Name:**  
  
**Date:**                      10-10-2025 11:57 AM

**Signature**