



Leak Check Report

Customer No.: 1915000 **Customer** Angel Velazquez
Name:
Date of 10-28-2025 10:55 AM **Ticket** 31577529
Inspection: **Number:**
CSC Location: 6402 Lumberton, NC

Customer Information

Service Address: 669 Veterans Rd St Pauls NC 28384
Billing Address: 669 Veterans Rd St Pauls NC 28384
Tank ID:: 2996690
Tank RINNAI RE140EP
Description:

Test Results

Type of Test: 0-30 High Pressure Test **Line Presssure:** 12 psi
Gauge
Start 5 psi **End Pressure:** 5 psi
Pressure:
Start Time: 10-28-2025 10:40 AM **End Time:** 10-28-2025 10:47 AM
Test Status: Pass **Tagged &**
locked:

Reason:
Leak Check includes all stages

Employee Acknowledgement

Employee Harbin, Jamie
Name:

Date: 10-28-2025 10:55 AM

Signature