

Jernigan Oil Company  
P.O. Box 688  
Ahoskie, NC 27910

Account Nr: 01-11152

Invoice Number: S769273

Bill To:

Ship To:

JR WILLIAM EDWARD BOOTS  
1401 ROUTE 588  
FOMBELL, PA 16123

JR WILLIAM EDWARD BOOTS  
12346 NC 903  
HAMILTON, NC 27840

I N V O I C E

Terms: Net 30 Days

Part Number	Description	Quantity	Price	Amount
COPPER 1/2	COPPER COATED 1/2	38.0	4.99	189.62
NS4 1/2	FLARE NUT HEAVY 1/2	6.0	2.60	15.60
44 1/2	FLARE TEE 1/2	1.0	3.99	3.99
MEGR-1252-D	COMPACT BACK MOUNT LOW PRE	2.0	59.99	119.98
1/2CAP	BLACK STEEL CAP 1/2	2.0	1.99	3.98
M1/2 ST ELB	BLACK STEEL ELBOW 1/2ST	2.0	6.99	13.98
1/2NIPP	BLACK STEEL NIPPLE 1/2 X 6	2.0	7.99	15.98
1/2X2NIPP	BLACK STEEL NIPPLE 1/2 X 2	2.0	6.99	13.98
M1/2 TEE	BLACK STEEL TEE 1/2	2.0	7.99	15.98
1/2UNION	BLACK STEEL UNION 1/2	2.0	15.99	31.98
	PROPANE LABOR	2.0	90.00	180.00
	LABOR (HELPER)	2.0	50.00	100.00
2SH069135	TANK SET	1.0	100.00	100.00
	RENT ADJUSTMENT	1.0-	100.00	100.00-
	RESIDENTIAL PROPANE	16.0	2.7999	44.80
	INSPECTION FEE	1.0	.0000	
	Sales Tax			52.49
				<hr/> 802.36

set 325 (2sh069135) @5% and ran lines to 2 gas  
packs

eMailed to: ed.boots101@gmail.com

# Bowen Heating, Air & Refrigeration, Inc.

1120 Tyner Road, Williamston, NC 27892

Phone 252-809-0226 Fax 252-792-3748

H-3,H-2 #20061 Ref#3709 Electrical #28789-L

YOUR COMFORT IS OUR BUSINESS!!

Invoice	Date	Due Date	Summary	Tech:
45891	12/18/2024	12/27/2024	INSTALLATION	OG

## Bill To:

Ed & Marla Boots  
12346 NC 903  
Hamilton, NC 27840

## Job Name:

Ed & Marla Boots  
12346 NC 903  
Hamilton, NC 27840

**PAID**

724-622-2665

724-622-2665

Item Code	Description	Hrs/Qty	Price	Amount
<p>For the downstairs front area, we installed a new American Standard 3.0 ton 15Seer package dual fuel system with new ductwork and central return. Outside unit sets on a pad. One new thermostat with outdoor sensor and one carbon monoxide detector were installed. We installed electrical wiring to this equipment. We supplied all materials and labor to install this equipment. NOTE: Air filter for this system is 20x30x1. For maximum efficiency, monthly non pleated air filter replacement is recommended.</p> <p>For the downstairs back area, we installed a new American Standard 3.0 ton 15Seer package dual fuel system with new ductwork and central return. Outside unit sets on a pad. One new thermostat with outdoor sensor was installed. We installed electrical wiring to this equipment. We supplied all materials and labor to install this equipment. NOTE: Air filter for this system is 20x30x1. For maximum efficiency, monthly non pleated air filter replacement is recommended.</p> <p>12/20/24--Gas tank and gas line are set. Fired up new systems.</p>				
American Standard 3.0 ton 15Seer package dual fuel and materials used for installation		1.00		
Model # 4DCZ5036E1070A	Serial # 24192521FA			
Warranty on dual fuels: 20 years heat exchanger; 10 years compressor; 5 years parts and coils; 1 year labor, thermostat, puron, outdoor sensor, carbon monoxide detector and ductwork. NOTE: Ductwork warranty does not cover water and/or animal damage.				
HW 8000 thermostat		1.00		
American Standard 3.0 ton 15Seer package dual fuel system and materials used for installaiton		1.00		
Model # 4DCZ5036E1070A	Serial # 232411403L			
HW 8000 thermostat		1.00		
Martin County permit		1.00		
Services		1.00		26606.00
Subtotal				Total
26606.00				\$26,606.00
Credits:				\$26,606.00 CR
Balance:				\$0.00

All material is guaranteed to be as specified. All work to be completed in a professional manner according to standard practices. Any alteration or deviation from above specifications involving extra costs will be executed only upon written orders and will become an extra charge over and above