



# Leak Check Report

Customer No.: 1842210 Customer Name: His & Hers Beauty Shop  
 Date of Inspection: 11-12-2024 02:00 PM Ticket Number: 24039512  
 CSC Location: 6402 Lumberton, NC

## Customer Information

Service Address: 3018 Old Whiteville Road Lumberton NC 28358  
 Billing Address: 3018 Old Whiteville Road Lumberton NC 28358  
 Tank ID:: 2896626  
 Tank: RINNAI RE140EP WATER HEATER  
 Description:

## Test Results

Type of Test: 0-30 High Pressure Test Gauge Line Pressure: 12 psi  
 Start Pressure: 5 psi End Pressure: 5 psi  
 Start Time: 11-12-2024 02:05 PM End Time: 11-12-2024 02:15 PM  
 Test Status: Pass Tagged & locked:

Reason:  
 Leak Check includes all stages

## Service Technician Acknowledgement

Technician Name: Christopher ward  
 Date: 11-12-2024 02:19 PM

Signature