

Leak Check Report

Customer No.: 2105060 **Customer** Wash & Dryve -holtsom
Date of 12-27-2024 12:15 PM **Name:** Ventures
Inspection: **Ticket** 18683064
CSC Location: 6402 Lumberton, NC **Number:**

Customer Information

Service Address: 2917 Old Orchard Rd NE CEDAR RAPIDS IA 52402
Billing Address: 2917 Old Orchard Rd NE CEDAR RAPIDS IA 52402
Tank ID:: 478627
Tank #7 Propane Tank 1542243 330G
Description:

Test Results

Type of Test: 0-30 High Pressure Test **Line Presssure:** 13 psi
Gauge
Start 5 psi **End Pressure:** 5 psi
Pressure:
Start Time: 12-27-2024 12:20 PM **End Time:** 12-27-2024 12:30 PM
Test Status: Pass **Tagged & locked:**

Reason:
Leak Check includes all stages

Service Technician Acknowledgement

Technician
Name: Ward, Christopher M.

Date: 12-27-2024 03:33 PM



Signature