



## Leak Check Report

Customer No.: 2102190 Customer Name: THOMAS INMAN  
Date of Inspection: 06-04-2025 10:13 AM Ticket Number:  
CSC Location: 6402 Lumberton, NC

### Customer Information

Service Address: 120 JOAN ST LUMBERTON NC 28358  
Billing Address: 120 JOAN ST LUMBERTON NC 28358  
Tank ID:: 481251  
Tank 500 sn 1005109 500G  
Description:

### Test Results

Type of Test: 0-30 High Pressure Test Gauge Line Pressure: 10 psi  
Start Pressure: 5 psi End Pressure: 5 psi  
Start Time: 06-04-2025 10:05 AM End Time: 06-04-2025 10:10 AM  
Test Status: Pass Tagged & locked:

Reason:  
Leak Check includes all stages

### Employee Acknowledgement

Employee Name: Hunt, Wesley

Date: 06-04-2025 10:13 AM

A handwritten signature in black ink, appearing to read "Wesley Hunt", written over a faint, larger signature.

Signature