



Family Owned & NC Grown
www.gbenergy.com

REMIT TO:
G&B ENERGY
P.O. BOX 811
ELKIN, NC 28621

G&B ENERGY - MILLERS CREEK
PO BOX 600
MILLERS CREEK, NC 28651
336-973-2411

*** SERVICE INVOICE *** 83256 ***

GUILLERMO PATINO
1615 BAYSHORE DR
MIAMI, FL 33133

ACCT# 541898 12/30/25

RETURN TOP PORTION WITH YOUR REMITTANCE.
SVC# 2

QUANTITY	DESCRIPTION	AMOUNT
1.000	PRESSURE TEST	
1.000	BALL VALVE 3/4 X 3/4	43.78
3.000	NIPPLE 3/4	12.24
1.000	TEE 3/4	5.70
1.000	CAP 3/4" BLACK STEEL	6.04
1.000	RINNAI TANKLESS WATER HEATER 160K BTU	895.00
1.000	NIPPLE 3/4 X 3	4.21
1.000	2 PSI REG. MAXITROL 3/4" T325-5L	90.00
	TOTAL PARTS	1056.97
	TOTAL LABOR 1.00 HOURS	400.00
	NC SALES TAX	101.99
	WHITE GOODS TAX	3.00

<<< TOTAL CHARGE FOR INVOICE # 83256 >>> 1561.96

* CONTINUED * PAGE 1



Family Owned & NC Grown
www.gbenergy.com

REMIT TO:

G&B ENERGY - MILLERS CREEK
PO BOX 600
MILLERS CREEK, NC 28651
336-973-2411

G&B ENERGY
P.O. BOX 811
ELKIN, NC 28621

*** SERVICE INVOICE *** 83256 ***

GUILLERMO PATINO
1615 BAYSHORE DR
MIAMI, FL 33133

ACCT# 541898 12/30/25

RETURN TOP PORTION WITH YOUR REMITTANCE.

SVC# 2

















QUANTITY	DESCRIPTION	AMOUNT
	SITE:GUILLERMO PATINO/254 PINNACLE DRIVE/./BOOMER NC 28606	
	DISPATCH DATE: 12/30/25	
	CALL REASONS: INSTALLATION	
	INSTALLED NEW WATER HEATER. MADE REPAIRS TO PLUMBING.	
	ADDED MAXITROL FOR PROPER GAS PRESSURE. LEAK TEST ON GAS	
	SYSTEM. TEST FIRED UNIT.	

PAGE 2

Date 12-30-25 Technician WV/DB Time In 2:18 Time Out 4:25

Customer Name Guillermo Patino Tubing 3/8 1/2 5/8

Account Number 541898 KC Tubing 3/8 1/2

 Flare Nut	NS-4	3/8	 Male Flare X Male Pipe Elbow	49	3/8x1/4
	NS-4	1/2		49	3/8x3/8
	NS-4	5/8		49	3/8x1/2
	NRS-4	1/2x3/8		49	3/8x3/4
 Flare Cap	26	3/8	 Male Flare X Male Pipe Union	49	1/2x1/4
	26	1/2		49	1/2x3/8
	26	5/8		49	1/2x1/2
 Flare Plug	27	3/8	 Male Flare X Male Pipe Union	49	1/2x3/4
	27	1/2		49	5/8x3/8
	27	5/8		49	5/8x1/2
 Flare Union	42	3/8	 Male Flare X Male Pipe Union	49	5/8x3/4
	42	1/2		48	1/4x1/4
	42	5/8		48	3/8x1/4
	42R	3/8x1/4		48	3/8x3/8
	42R	1/2x3/8		48	3/8x1/2
	42R	5/8x3/8		48	3/8x3/4
 Flare Elbow	42R	5/8x1/2	 Male Flare X Male Pipe Union	48	1/2x1/4
	55	3/8		48	1/2x3/8
	55	1/2		48	1/2x1/2
	55	5/8		48	1/2x3/4
	55R	1/2x3/8		48	5/8x3/8
	55R	5/8x3/8		48	5/8x1/2
 Flare Tee	55R	5/8x1/2	 Male Flare X Female Pipe Elbow	48	5/8x3/4
	44	3/8		54	3/8x3/8
	44	1/2		54	3/8x1/2
	44	5/8		54	3/8x3/8
	44R	3/8x3/8x1/2		54	1/2x3/8
	44R	1/2x3/8x3/8		54	1/2x1/2
 Gas Ball Valve Flare X Flare M Flare X Female Pipe	44R	1/2x1/2x3/8	 Male Flare X Female Pipe Union	54	1/2x3/4
	44R	5/8x5/8x3/8		54	5/8x1/2
	44R	5/8x5/8x1/2		54	5/8x3/4
	T200	3/8		46	3/8x1/4
	T200	1/2		46	3/8x3/8
	T200	5/8		46	3/8x1/2
 F. Pipe X F. Pipe	500	3/8x1/2	 Male Flare X Female Pipe Union	46	3/8x3/4
	500	1/2x1/2		46	1/2x3/8
	500	5/8x3/4		46	1/2x1/2
	T300	3/8x3/8		46	1/2x3/4
	T300	1/2x1/2		46	5/8x3/8
	T300	3/4x3/4		46	5/8x1/2
T300	1x1	46	5/8x3/4		

1/2"	3/8"
Pipe <u>PI1/2S4OT</u>	Pipe <u>PI3/8S4OT</u>
Nipple <u>NIP1/2</u>	Nipple <u>NIP3/8</u>
Ell <u>EL1/290</u>	Ell <u>EL3/890</u>
Street L <u>EL1/290ST</u>	Street L <u>EL3/890ST</u>
Tee <u>TEE1/2</u>	Tee <u>TEE3/8</u>
Union <u>UN1/2</u>	Union <u>UN3/8</u>
Cap <u>CAP1/2</u>	Cap <u>CAP3/8</u>
Reducer <u>x</u>	Reducer <u>x</u>

3/4"	1"
Pipe <u>PI3/4S4OT</u>	Pipe <u>PI1S4OT</u>
Nipple <u>NIP3/4</u>	Nipple <u>NIP1</u>
Ell <u>EL3/490</u>	Ell <u>EL190</u>
Street L <u>EL3/490ST</u>	Street L <u>EL190ST</u>
Tee <u>TEE3/4</u>	Tee <u>TEE1</u>
Union <u>UN3/4</u>	Union <u>UN1</u>
Cap <u>CAP3/4</u>	Cap <u>CAP1</u>
Reducer <u>x</u>	Reducer <u>x</u>

Appliance Model Serial _____
 Appliance Model Serial _____
 Appliance Model Serial _____



Model:RE180P
 (REU-VE2432FFD-US)
 Serial:TF.UA-086990

3/4 x 3/8 Nip = 1
3/4 Maxi Tub = 1

Contract Labor _____

CO Detector? yes no
 If customer supplied: Signature _____

Miscellaneous Parts and Comments
Leak test Passed. Installed New Hotwater Heater.
Installed Maxi Tub,